
MALAYSIA

CIVIL AVIATION AUTHORITY OF MALAYSIA
AERONAUTICAL INFORMATION SERVICES
AIR TRAFFIC CONTROL TOWER (TOWER WEST)
JALAN KLIA 2/4,
64000 KLIA,
SELANGOR DARUL EHSAN
MALAYSIA.

PHONE: 6-03-8778 4106
Email ais@caam.gov.my
URL: aip.caam.gov.my

**AIRAC AIP SUP
45/25**
**Effective Date: 04 SEP 2025
to UFN**
Publication Date: 24 JUL 2025

**LABUAN AIRPORT (WBKL)
HIGH TREES CAUSE OBSTRUCTED LINE-OF-SIGHT TO TOWER**

1 INTRODUCTION

1.1 This AIRAC AIP Supplement is to inform all concerned as follows:

1.1.1 Pilots to exercise caution and report any abnormal situation within area on the runway between TWY D and TWY G, including turning pad RWY 14/32 due to high trees cause obstructed line-of-sight to tower.

2 CONTACTS

2.1 Any information and queries to contact:

Name/designated : Labuan Tower / Duty Air Traffic Control Officer (DATCO)
TEL : +6087 - 412459 / +6011 - 63477664
Email : wbkl.2020@gmail.com

3 VALIDITY

3.1 This AIRAC AIP Supplement supersedes **NOTAM D0774/25** and will remain in force until further notice. Any updates, changes and cancellation to this AIRAC AIP Supplement will be notified through NOTAM.

- END -