
TEL : 6-03-8529 1318
FAX : 6-03-8529 1310
Email : ais@caam.gov.my
Web : aip.caam.gov.my

MALAYSIA
CIVIL AVIATION AUTHORITY OF MALAYSIA
AERONAUTICAL INFORMATION SERVICES
LEVEL 2, WEST WING TERMINAL NORTH
JALAN CTA 3
KUALA LUMPUR INTERNATIONAL AIRPORT
64000 KLIA, SEPANG
SELANGOR DARUL EHSAN

**AIP SUP
23/2024**

Effective from 21 MAR 2024
to UFN
Published on 21 MAR 2024

**KUALA LUMPUR INTERNATIONAL AIRPORT (WMKK)
WORK IN PROGRESS**

(This AIP Supplement replaces AIP Supplement 39/2023)

1. **INTRODUCTION**

- 1.1 The following temporary changes concerning Kuala Lumpur International Airport Aerodrome (WMKK) concerning to aircraft stand B3 temporarily closed WIE until further notice.

WMKK AD 2.24 CHARTS RELATED TO AN AERODROME

Refer AIP AD-2-WMKK-2-5 Aircraft parking/docking chart (WMKK) - ICAO, AD 2-WMKK-2-12 Aircraft Parking Docking (Tabular 1), portion of Aircraft Stand Taxilane T12 abeam aircraft stand B3 closed.

Aircraft are only allowed to start up engine abeam Aircraft Stand B9 for safety.

WMKK AD 2.20 LOCAL TRAFFIC REGULATIONS

2.20.10 Jet Blast Procedures

Non-Standard Pushback Procedures at Aircraft Stand B5 and B7. Aircraft to be pushed back and towed forward until abeam Aircraft Stand B9 before taxiing out. Engine start at the aircraft stand is prohibited. Engine start is only permitted abeam Aircraft Stand B9.

2. **VALIDITY**

- 2.1 This AIP Supplement supersedes **AIP SUP 39/2023** dated 09th November 2023 and will remain in force until further notice. Any changes to this AIP Supplement will be notified through NOTAM.

- END -